

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



1/15




FIGURE 1



200

2/15




FIGURE 2



IN-LINE FRONT-OF-LINE PORTION
300A




FIGURE 3A




4/15

IN-LINE END-OF-LINE PORTION
300B

V/C 302	V/C 302	V/C 302
MOLD 314	PMC 316	SBA 318
	SAW 320	SORT 322

FIGURE 3B



5/15

IN-LINE FINISH PORTION

300C

V/C 302	V/C 302	V/C 302
MARK 324	FVI 326	T/R 328

FIGURE 3C



6/15





FIGURE 4



7/15




FIGURE 5





9/15





FIGURE 7



10/15

800





FIGURE 8



11/15

900




FIGURE 9



12/15

1000





FIGURE 10



13/15

1100




FIGURE 11






FIGURE 12



15/15

1350




FIGURE 13